Castable Plus Black (S-CST1BK)

Check:

- Well shakened resin (>60 seconds)Clean optical pathwaysGood resin tank condition

Print Settings:

Printer	Layer Thickness (μm)	Normal Layer Exposure Time (s)	Bottom Layer Exposure Time (s)	Lifting Distance (mm)	Lifting Speed (mm/min)	Retract Speed (mm/min)	
Anycubic	50	8	32	7 + 1	1+1	2.5 + 2.5	
Photon M3 Premium					(mm/s)	(mm/s)	
Anycubic	50	5	20	7 + 1	1+1	2.5 + 2.5	
Photon Mono X 6K					(mm/s)	(mm/s)	
Anycubic	50	10	40	4 + 1	1 + 1	2.5 + 2.5	
Photon Mono 4 Ultra					(mm/s)	(mm/s)	
Elegoo Mars 2 Pro	50	8	32	4 + 1	60 + 60	150 + 150	
Elegoo Mars 3 Pro	50	9	36	4 + 1	60 + 60	150 + 150	
Elegoo Mars 4	50	5	20	4 + 1	60 + 60	150 + 150	
Elegoo Mars 4 DLP	50	5	20	4 + 1	60 + 60	150 + 150	
Elegoo Mars 5 Ultra	50	9	60	-	-	-	
Elegoo Saturn S	50	8	32	7 + 1	60 + 60	150 + 150	
Elegoo Saturn 3 Ultra	50	9	36	7 + 1	60 + 60	150 + 150	
Elegoo Saturn 4	50	9	36	7 + 1	60 + 60	150 + 150	
Elegoo Saturn 4 Ultra	50	10	40	-	-	-	
Phrozen	30	9	36	4 + 1	60 + 60	150 + 150	
Sonic mini 8K	50	11	44	4 + 1	60 + 60	150 + 150	
Phrozen	30	9	36	4 + 1	60 + 60	150 + 150	
Sonic mini 8K S	50	11	44	4 + 1	60 + 60	150 + 150	
Phrozen	50	16	64	7 + 1	60 + 60	150 + 150	
Sonic Mighty12K							
Phrozen	50	12	48	7 + 1	60 + 60	150 + 150	
Sonic Mighty Revo	00	12	10	,	00 1 00	100 - 100	
		Download above .cfgx file from support page					
Asiga Max UV385 Asiga PRO 4K UV385	25						
	50		Download .ini file from support page				
	25						
	50						
Formlabs Form 4/4B	25		Download fr	as file from a	Innort nage		
	50	Download .fps file from <u>support</u> page					
SprintRay Pro2	50	Sprintray Castable 2 (Not endorsed by SprintRay)					
SprintRay Pro95S	50	Sprintray Castable 2 (Not endorsed by SprintRay)					
HeyGears Reflex	30	PAC10					

Each printer is unique, and light intensity can vary even among identical models. Minor adjustments may be necessary, especially true for open-system MSLA printers.

Download printer setting profiles via ApplyLabWork <u>Support</u> page, or download <u>Exposure Settings Data Sheet (Excel)</u>. For size calibration, download the <u>stl file</u>.

Washing:

Rinse with fresh IPA (95% purity or higher) or apply sonication for 2 minutes. Blow dry via compressor air immediately after wash. The surface may turn grayish, especially with ultrasonic washing, no effect on casting result.

Limit IPA contact time to 2 minutes, prolong contact time could cause deformation.

Drying:

Let models **sit dry 60 minutes minimum** in a shaded airy place. Printed parts must be free of IPA before casting. Residual IPA (if not dried completely) could cause deformation.

No Post-Curing required

Storage:

Filter out all debris in used-resin before storage. Keep resin in the original bottle, storage temp (15-26°C / 59-79°F) in a dry and dark area.

Note, slight pigment settlement is normal. Gently mix remaining resin in resin tank with soft "resin wiper" for color evenness.

Casting

Investment

Castable Plus Black is compatible with most kind of gypsum-bonded investment.

For optimal results, please consider investments designed for 3D printed resins.

Example: R&R Plasticast, Optima Prestige, Gold Star Resincast or equivalent.

Water/powder ratio of $37/100 \sim 38/100$.

Let flask set for at least 2 hours prior to the burnout.

Prints

Allow the prints dry for at least 60 mins before assembling the cast tree.


Consider using 'Sticky Wax' to ensure strong adhesion between models and wax tree. Include sprues with model design when possible to simplify printing support structure and tree building.

Burnout Schedule

Example: Burnout schedule for a 3-3/8"x4" vacuum flask.

- 1. Start kiln at room temperature or preheated to 150°C (302°F)
- 2. Hold 150°C (302°F) for 3 hours
- 3. Raise temperature to 750°C (1382°F) in 2 hours.
- 4. Hold 750°C (1382°F) for 3 hours (for large flask, let sit for 1-2 hours longer)
- 5. Reduce to casting temperature (for example, 430°C (806°F) for sterling silver)
- 6. Hold Casting Temperature for at least 2 hours

Note: Do Not Exceed Maximum Temperature (refer to manufacturer instructions)



Specialty Resin
Page 3 of 9

Casting Tips Geometric shape/sharp edge hole:



- 1. Feeding system: make sure the joints are well-rounded and fully heated solder joints
- 2. Models position: leave adequate space between models
- 3. Water/powder ratio: decrease water/powder ration to increase investment strength

Rough surface (texture)



1. Accelerate temperature ramp

2. Investment: follow the instructions of manufacturer, correct amount of water/powder ratio, fully mixed, place flask on stable surface for setting, do not disturb for 2 hours





1. Temperature: decrease the temperature of metal or flask (check the recommend temperature from supplier and adjust according geometry of model and size of flask)

Incomplete filling:



Specialty Resin Page 5 of 9

- 1. Temperature: Increase the temperature of metal or flask (check the recommend temperature from supplier and adjust according geometry of model and size of flask)
- 2. Feeding system: increase sprue's diameter or amount

Small porosity / Dark inclusions:



1. Incomplete burnout:

- i. Extend the maximum temperature hold time for 1 ~ 2 hours
- ii. Turn the flask upside down (pouring cone up) during the last hour of maximum temperature
- iii. Open the door couple times during the maximum temperature
- iv. Accelerate temperature ramp

Fin (Flashing):



Specialty Resin
Page 6 of 9

- 1. Models position: leave adequate space between models, and between models and flask
- 2. Water/powder ratio: decrease water/powder ratio to increase investment strength
- 3. Investment: drying out the investment too long may cause cracking, refer to manufacturer instructions
- 4. Overheat the flask during burnout: refer to manufacturer instructions for the maximum temperature

ApplyLabWork Castable Investment Friendliness Test R&R Ultravest vs. R&R Plasticast

Metal: Brass 1060°C / Flask 650°C Investment water-powder ratio: 38:100

Flask: 3-3/8"x4" vacuum flask

Flask orientation: Keep sprue facing downward throughout the entire burnout

process

Casting Machine: Vacuum Casting Machine

R&R Ultravest

R&R Plasticast





R&R Ultravest

R&R Plasticast





R&R Ultravest



R&R Plasticast



R&R Ultravest



R&R Plasticast



R&R Ultravest



R&R Plasticast



R&R Ultravest



R&R Plasticast



Specialty Resin Page 9 of 9